"Missing Links" Report
25 July 2014

Mrs. YEUNG HO Poi Yan, Ingrid, JP
Commissioner for Transport
41/F, Immigration Tower
7 Gloucester Road, Wan Chai, Hong Kong   By post and email: comr@td.gov.hk

Mr HON Chi Keung, JP
Director of Civil Engineering
CEDD Building
101 Princess Margaret Road
Ho Man Tin, Kowloon   By post and email: ckhon@cedd.gov.hk

Kennedy Road - 11SW-B/CR124 - Landslip Prevention - Hong Kong Island

Dear Sirs and Madams

The footpath along Kennedy Road are sub-standard and missing for some sections.

Director of CEDD, kindly please advise:

1. What is the scope, boundary and program for 11SW-B/CR124?
2. Will 11SW-B/CR124 include enhancement of footpath? Will it include enhancing the missing section indicated in the attached presentation? If yes, when will it be completed?
3. If not included, is the slope beneath the missing footpath intended to be included under any landslip or slope works program, and if so, what is that program and what is the targeted date for works to commence?

Commissioner of Transport, kindly please advise:

1.   What efforts have been made to provide a footway for the missing section of footpath along Kennedy Road? When will a footway be provided and what width will that footway be?

"Missing Links" Report

2.   If you have no plan or program in place, how do you justify approval of TIAs and 'no objections' for new developments along and near Kennedy Road?

Enclosed please find the location with photo and information. Please feel free to contact Mr. Leung at 3104-2766 or denis@designinghongkong.com if you have any questions.

Yours sincerely,

Paul Zimmerman, CEO of Designing Hong Kong
www.missinglinks.hk

c.c. Chairman and Members of Central and Western District Council (cwdcadm@cwdc.had.gov.hk)
Encl. Photos of Kennedy Road

"Missing Links" Report