

土力工程處

Geotechnical Engineering Office

Web site

網址

: http://www.cedd.gov.hk

E-mail Telephone

電話

電子郵件: ylam@cedd.gov.hk : (852) 2760 5811

Facsimile

傳真

: (852) 2624 4135

Our ref

Your ref 來函檔號:

本署檔號: LPM/(GE/2013/27)/M10/300

By fax and post – Fax no. 2187 2305

土木工程拓展署大樓 Civil Engineering and Development Building, 101 Princess Margaret Road,

香港九龍公主道 101 號

Kowloon, Hong Kong

6 August 2014

**Designing Hong Kong** Unit 7, 5/F, Eastern Harbour Centre, 28 Hoi Chak Street, Quarry Bay, Hong Kong (Attn: Mr. Paul Zimmerman)

Dear Sirs,

## Slope No. 11SW-B/CR124 Location: Below Kennedy Road near Hong Kong Park

Your letter dated 25 July 2014 to our Director Mr. Hon Chi Keung expressing concerns on the missing footpath along Kennedy Road near the captioned slope refers. The letter is referred to me for attention and follow-up action.

CEDD is currently upgrading the slope 11SW-B/CR124 using soil nails and the works will be completed in August 2014. The slope boundary and the extent of the works site and works area are shown on the location plan attached.

The slope upgrading works at 11SW-B/CR124 do not include enhancement of footpath. There is no registered man-made slope or vulnerable natural terrain catchment beneath the area of concern and CEDD currently has no plan to carry out any slope works in that area.

Should you have any further question on the subject matter, please do not hesitate to contact me or my colleague Mr. C M Mak at 2762 5446 (e-mail: cmmak@cedd.gov.hk).

Yours faithfully,

(YLam)


Chief Geotechnical Engineer/LPM Division 1 Geotechnical Engineering Office Civil Engineering and Development Department

Encl.

Commissioner of Transport (Attn: Mr. Philip Lam, by e-mail: philipsklam@td.gov.hk) Communications Unit, CEDD HQ (Attn: Ms. Mandy Tam)

/CMM/EKSF/eksf 卓越工程 建設香港

We Engineer Hong Kong's Development



Works Area 1111

Approximate Site Boundary Approximate Hourding alignment