

創建 Designing HongKong 邊度冇路行? www.MissingLinks.hk 香港

香港灣仔告士打道 7 號
入境事務大樓 41 樓
運輸署署長 楊何蓓茵女士

郵寄及電郵：comr@td.gov.hk

灣仔軒尼詩道 130 號
修頓中心 21 樓
灣仔區區議會主席及議員

郵寄及電郵：wcdcadm@wcdc.had.gov.hk

灣仔區區內不合標準和缺乏連接的行人路

敬啟者：

我們的活動「邊度冇路行」以改善香港行人路的連接性為目標，在過去一年，市民通過我們的網站 (www.missinglinks.hk) 報告了各區狹窄或不合標準的行人路和缺乏過路處的地點。

我們現將第二輪從民間收集到的相關地點提供予運輸署及灣仔區區議會，希望運輸署和灣仔區區議會能共同改善有關的行人路和過路處，令灣仔區的居民和遊客能夠享有安全而便捷的行人路。

隨信附上的照片和相關地點的列表。如有查詢，請聯絡創建香港梁先生 3104-2766 或 denis@designinghongkong.com。如有任何更新資訊，請隨時聯絡我們，以便告知相關的公眾。

此致

運輸署署長楊何蓓茵女士及灣仔區區議會主席及議員 鈞鑒

司馬文
創建香港行政總裁

二零一四年十二月十七日

隨函附上兩個「邊到冇路行？」之詳細報告

創建 Designing Hong Kong 邊度冇路行? www.MissingLinks.hk 香港

17 December 2014

Mrs. YEUNG HO Poi Yan, Ingrid, JP
Commissioner for Transport
41/F, Immigration Tower
7 Gloucester Road, Wan Chai, Hong Kong

By post and email: comr@td.gov.hk

Chairman and Members of Wan Chai District Council
21/F, Southorn Centre,
130 Hennessy Road, Wan Chai

By post and email: wcdcadm@wcdc.had.gov.hk

Missing and sub-standard pedestrian connections in the Wan Chai District

Dear Sirs and Madams

Our campaign 'Missing Links' began a year ago with the objective of improving pedestrian connections in Hong Kong. Via our website (www.missinglinks.hk), the public has identified locations where footpaths or crossings are either missing, narrow or sub-standard.

We are bringing a secondary relevant locations identified by the community to your attention and we would be grateful if Transport Department and the Wan Chai District Council would work together to improve these pedestrian connections for the benefits of residents and visitors of the Wan Chai District.

Enclosed please find a list of locations with photos and information. Please feel free to contact Mr. Leung at 3104-2766 or denis@designinghongkong.com if you have any questions. Keep us posted on the result so that we can inform the public accordingly.

Yours sincerely,

Paul Zimmerman, CEO of Designing Hong Kong

Encl. Maps and photos of 2 Missing Links

創建 Designing Hong Kong

邊度冇路行? www.MissingLinks.hk 香港

1.

Location: Entrance of Ruttonjee Hospital at Queen's Road East

Problem: Unsafe Crossing

Description: Unsafe crossing with traffic from three directions entering the hospital at any time


Suggestion: Provide zebra and/or signalised crossing

位置： 皇后大道東律敦治醫院入口

問題： 過路處不安全

詳情： 過路處不安全，因汽車可不定時由三個不同方向進入醫院

建議： 提供斑馬綫和/或交通燈控制的過路處



創建 Designing Hong Kong

邊度冇路行? www.MissingLinks.hk 香港

2.

Location: Mount Butler Road

Problem: Missing footpath

Suggestion: Provide footpath

位置： 畢拉山道

問題： 缺乏行人路

建議： 提供行人路

